

HIROSHIMA, JAPAN - BAMBOO BARRIER™ RHIZOME PRUNING PROJECT

PRODUCT: WB 36

Rhizomes from the adjacent bamboo forest were causing this multi-use path in Hiroshima, Japan to buckle and heave. Tired of the on-going problem and costly repairs the local authorities sought a more permanent solution. After removal of the damaged asphalt a trench was dug and the rhizomes pruned. DeepRoot WB 36 was then installed to block future surface rhizome growth.



Damaged Multi-Use path



Detail of path



Surface rhizomes



BambooBarrier™ installed